

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Cherron USA Inc.				API Number 30-025-25712				
Property Name Central Vacuum Unit						Well No. 101		
7. Surface Location								
UL - Lot. 6	Section 6	Township 182	Range 35E	Feet from 1410	N/S Line FNL	Feet From 1336	E/W Line FEL	County LEA

Well Status

Well Status	Actual	PRODUCING	DATE
✓ IA		✓ Im	11/18/2013

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Intern	(B)Intern(1)-Intern(2)	(C)Intern-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	D	O	O	e	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

> Injection Reported 10/2013 (Water - 16142 BBS)
SAD 11/13/2014

Resp Violation 1/28/00

Accepted for Record Only

— MMB

Signature: 		OIL CONSERVATION DIVISION
Printed name: Danny Acosta		Entered into RBDMs
Title: ALER		Re-test
E-mail Address: DNLC@chevron.com		
Date: 4/18/2013	Phone: 575-631-9033	
	Witness:	

JAN 27 2014