

DEC 13 2013

RECEIVED

1625 N. Lincoln Dr., Hobbs, NM 88240
Phone: (505) 398-6101 Fax: (505) 393-3729

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 3002525728
Property Name (1VV) Central Vacuum Unit	Well No. 73

Surface Location									
ML Loc H	Section 36	Township 17S	Range 34E	Feet East 2630	Section N	Feet East 142	East Side E	County LEA	

Well Status			
Well Status A	STATUS Producing	DATE 11/18/13	

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm.	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-1 above	(E) 1 above
Pressure	0		0	775	
Flow Characteristics					
Pool	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Flow to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

TKg is cmt'd in Well. Special Annual MIT.

Accepted for Record Only
MKB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Gary Acker	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: gack@chevron.com	
Date: 11/18/13	Phone: 575-6719033
Witness:	

JAN 27 2014

[Handwritten mark]