

DEC 18 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ <i>Chevron USA, Inc</i>	API Number <i>30-025-3810</i>
Property Name ✓ <i>Central Vacuum Unit</i>	Well No. <i>244</i>

7. Surface Location

UL Lot ✓ <i>B</i>	Section <i>6</i>	Township <i>18N</i>	Range <i>35E</i>	Feet from <i>10</i>	N/S Line <i>FNL</i>	Feet From <i>1930</i>	E/W Line <i>FEL</i>	County <i>LEA</i>
-----------------------------	---------------------	------------------------	---------------------	------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN ✓	PRODUCING ✗ <i>Inj</i>	DATE <i>10-29-13</i>
-------------------------	---------------------	----------------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	<i>0</i>		<i>500 #</i>		
Flow Characteristics					
Puff	Y / N	Y / N	Y / ✗	Y / N	
Steady Flow	Y / N	Y / N	✗ / N	Y / N	
Surges	Y / N	Y / N	Y / ✗	Y / N	
Down to nothing	Y / N	Y / N	Y / ✗	Y / N	
Gas or Oil	Y / N	Y / N	✗ / N	Y / N	
Water	Y / N	Y / N	✗ / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

MIT Failed - Well Shut in.

> Violation Letter 1/2014

Accepted for Record Only

MSB 1/16/2014

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: <i>Danny Acosta</i>	Entered into RBIMS
Title: <i>ALCR</i>	Re-test
E-mail Address: <i>DNLAC@chevron.com</i>	
Date: <i>10-29-2013</i>	Phone: <i>575-631-9033</i>
Witness:	

JAN 27 2014

