

District 1

1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA Inc	API Number 30-025-35213
Property Name ✓ Central Vacuum Unit	Well No. 241

7. Surface Location

U/Lot ✓ B	Section 36	Township 17N	Range 34E	Feet from 74	N/S Line FNL	Feet From 1940	E/W Line FEL	County LEA
---------------------	----------------------	------------------------	---------------------	------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status ✓ A	SHUT-IN	PRODUCING ✓ Inj	DATE 10-25-13
---------------------------	---------	---------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	Ø		Ø	1552	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

1. CO₂ + Water Injection Reported 10/2013. WTH - 1500 CO₂ - 2200.
 2. 1552# Tubing Pressure Reported 10/2013. 84D/1/2014

FOR RECORD ONLY

WAS/OGD

Signature: Danny Acosta	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBEMS
Title: ALCR	Re-test
E-mail Address: DNHC@chevron.com	
Date: 10-25-13	Phone: 575-631-9033
Witness:	

JAN 27 2014