

JAN 31 2014

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-10424
Property Name OT Boyd	Well No. 2

7. Surface Location										
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County	
0	23	22S	37E		Le60	FSL	1980	FEL	Lea	

Well Status

Well Status Active	SHUT-IN	PRODUCING Pumping	DATE 1/26/2014
------------------------------	---------	-----------------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Intern	(B)Intern(1)-Intern(2)	(C)Intern-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0	0		38	38
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

YMSB 2/4/2014

Signature: <i>JHobbs</i>	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: KUVV@chevron.com	
Date: 1/26/2014	Phone: 575-631-4228
Witness:	

FEB 05 2014