

HOBBS OCD

JAN 31 2014

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0230

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-25184
Property Name Central Drinkard Unit	Well No. 408

2. Surface Location

UL - Lot D	Section 28	Township 21S	Range 37E	Feet from 972	N/S Line FNL	Feet from 1305	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status SHUT-IN	SHUT-IN	PRODUCING YES	DATE 1/30/14
-------------------------------	---------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0			0	1500
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

> Inspection Violation re: Over Pressure Limit
JAD 2/5/14

Letter 2/5/14
of Violation N JAD

Accepted for Record Only

MSB 2/4/2014

Signature J Hobbs	OIL CONSERVATION DIVISION
Printed name Justin Hobbs	Entered into RBDMS
Title PSSS	Re-test
E-mail Address KUV@chevron.com	
Date 1/29/2014	Phone 575-631-4228
Witness:	

FEB 06 2014