

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OGD
FEB 05 2014

WELL API NO. 30-025-22797
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. Fee Property Lease (Sims)
7. Lease Name or Unit Agreement Name BD SWD Well H-35
8. Well Number H-35
9. OGRID Number 19174
10. Pool name or Wildcat Salt Water Disposal into San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO PLUG OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD

2. Name of Operator
Rice Operating, Co.

3. Address of Operator
118 West Taylor, Hobbs NM 88240

4. Well Location

Unit Letter H : 1872 feet from the N line and 233 feet from the E line
Section 35 Township 22S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3293' ASL

12. Check Appropriate Nature of Notice, Report or Other Data

PERFORM REMEDIAL WORK
TEMPORARY PLUGGING

NOTICE
Approved for Plugging of well bore only.
Liability under bond is retained pending receipt of C-103 (Specifically for Subsequent Report of Well Plugging) which may be found at OCD web page under forms!
www.emnrd.state.nm.us/oed

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of proposed completion or recompletion. SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This well has been plugged and abandoned. Please see attached procedure.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marvin Burrows TITLE Well Specialist DATE Feb 4, 2014

Type or print name Marvin Burrows E-mail address: mburrows@riceswd.com PHONE: 393-9174

For State Use Only

APPROVED BY: Malay Brown TITLE Compliance Officer DATE 2/7/2014

Conditions of Approval (if any):

Rice Operating Co.

BD SWD Well H-35.

API 30-025-22797

P&A

1/17/14 : Held safety meeting. MIRU Basic plugging rig. Spot and hook up all tanks and equipment. Filled tanks. SD.

1/20/14 : Held safety meeting. Broke wellhead connections down. Tubing running over. Put vac truck on cellar. Pulled 6" x 900 x 2 7/8" tubing hanger. Stripped on double BOP (2 7/8" and blanks). POH laying down 2 7/8" EUE IPC injection tubing. 100% recovery of 123 joints (3905') and bottom hole assembly. RU wireline. Ran gauge ring to 3905' OK. POH. Picked up 7" CIBP. Ran CIBP w/ wireline to 3905' and set. POH and RD wireline truck. Hauled in 2 3/8" work string. Started picking up work string. Winds high, threads crossing. SD 2 hours. Wait for wind to drop per forecast. Tallied and ran 100 jts 2 3/8" work string. Secured well. SDON.

1/21/14 : Held safety meeting. Finished PU work string. Ran to CIBP at 3905'. Mixed and displaced w/ MLF per OCD regulation. SI and PT to 400# OK. Mix and spot 35 sk plug from 3905'. Pull 20 stands tubing, SD for 3 hours. Ran tubing back to tag TOC at 3735' OK. POH to 2400'. Mix and spot 35 sk plug from 2400'. POH w/ 20 stands. Secured well. SDON to WOC.

1/22/14 : Held safety meeting. Ran tubing. Tagged TOC on last plug at 2231'. POH to end of tubing at 1232'. Pumped 35 sack plug. POH w/ 6 stands. WOC 3 hrs. Ran tubing back, tagged TOC at 1059'. POH to end of tubing at 210'. Filled casing to head w/ cement. POH and lay down remainder of tubing. Refilled casing w/ cement w/ hose. Rig work is completed.

1/30/14 : Cut off wellhead and deadman anchors. Welded P&A marker onto casing, filled cellar. Leveled location. Well is plugged and abandoned.

MLB 2/2/14