

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAR 07 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Mowbourne Oil Company	API Number 30-025-29770
Property Name CPBSSU 3	Well No. 2

Surface Location

UL - Lot 5	Section 23	Township 18S	Range 32E	Feet from 2310	N/S Line 5	Feet From 2030	E/W Line E	County Lca
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status A	SHUT-IN ?	Producing Injecting	DATE
-------------------------	---------------------	--	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(I)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure			0#	60#	1850#
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------


Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Well has 60# casing and had water coming out and die down to nothing in 2 seconds.

No Injection Reported
As of 7/2013. JAD 3/2014

Accepted for Record Only
MAB 3/10/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Antonio Martinez	Entered into RBDMS
Title: Production Engineer	Re-test
E-mail Address: amartinez@mowbourne.com	
Date: 2-20-14	Phone: (575) 390-1818
Witness:	

MAR 10 2014