

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAR 07 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <i>Newbourne Oil Company</i>	API Number <i>30-025-3115</i>
Property Name <i>OPBSU #6</i>	Well No. <i>161</i>

2. Surface Location

UL - Lot <i>24</i>	Section <i>185</i>	Township <i>32E</i>	Range <i>2310</i>	N/S Line <i>8</i>	Feet From <i>830</i>	E/W Line <i>W</i>	County <i>Lea</i>
-----------------------	-----------------------	------------------------	----------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status <i>SHUT-IN</i>	<i>Injecting</i>	DATE
-------------------------------	------------------	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure			<i>0#</i>	<i>0#</i>	<i>0#</i>
Flow Characteristics					
Puff	Y / N	Y / N	Y / <i>(N)</i>	<i>(Y)</i> / N	
Steady Flow	Y / N	Y / N	Y / <i>(N)</i>	Y / <i>(N)</i>	
Surges	Y / N	Y / N	Y / <i>(N)</i>	Y / <i>(N)</i>	
Down to nothing	Y / N	Y / N	<i>(Y)</i> / N	<i>(Y)</i> / N	
Gas or Oil	Y / N	Y / N	Y / <i>(N)</i>	Y / <i>(N)</i>	
Water	Y / N	Y / N	Y / <i>(N)</i>	Y / <i>(N)</i>	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

*> No Injection in 18 months
SAD 3/2014*

*> NOT Blm to P+A well
2/2013*

> Priming failure

Accepted for Record Only
MSB 3/10/2014

Signature: <i>Antonio Martinez</i>	OIL CONSERVATION DIVISION
Printed name: <i>Antonio Martinez</i>	Entered into RBDMS
Title: <i>Production Engineer</i>	Re-test
E-mail Address: <i>amartinez2@newbourne.com</i>	
Date: <i>2-20-14</i>	
Phone: <i>(575) 390-1818</i>	
Witness:	

MAR 10 2014