

HOBBS OCD

MAR 28

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Linn Energy	API Number 30-025-00528
Property Name Caprock Maljamar Unit	Well No. 13

2. Surface Location

UL - Lot J	Section 13	Township 17S	Range 32E	Feet from 1980	N/S Line F&L	Feet from 1980	E/W Line F&L	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------------	--------------------------	----------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 3/6/14	Injection Active
-------------	---------	-----------	-----------------------	----------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm 1-Interm 2	(C) Interm-Prod	(D) Prod Csg	(E) Tubing
Pressure	0			0	2200
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO₂

Did MIT at the same time, Failed MIT, SI. Injection Well, Didn't have anything on csg, or Braden head

Signature: Dan Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linnenergy.com	
Date: 3/6/14	Phone: 575-369-9113
Witness:	

MAR 31 2014

HOBBS OCD

HOBBS OCD

MAR 28

MAR 28

RECEIVED

RECEIVED

