

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAR 28 2014

BRADENHEAD TEST REPORT

RECEIVED
API Number

Operator Name Linn Energy	30-025-01467
Property Name Caprock Maljamar Unit	Well No. 2

2. Surface Location

UL - Lot A	Section 18	Township 17	Range R33E	Feet from 660	N/S Line FNL	Feet From 660	E/W Line FEL	County Lea
---------------	---------------	----------------	---------------	------------------	-----------------	------------------	-----------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 3/6/14	Injection Active
-------------	---------	-----------	----------------	---------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1)-Interm (2)	(C) Interm-Prod	(D) Prod Csg	(E) Tubing
Pressure	0			0	700
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	Y / (N)	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO₂

Did MIT at same time Failed. S.I injection well. Didn't have anything on csg or Braden head

Signature: Dan Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linenergy.com	
Date: 3/6/14	Phone: 575-369-9116
Witness:	

MAR 31 2014