

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAR 28 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Linn Operating	API Number 30-025-01485
Property Name Caprock Maljamar Unit	Well No. 38

2. Surface Location

UL - Lot C	Section 19	Township 17S	Range 33E	Feet from 660	NS Line FNL	Feet From 2047	EW Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	-----------------------	--------------------------	-----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 3/6/14	Injection Active
-------------	---------	-----------	-----------------------	----------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm 1-Interm 2	(C)Interm-Prod	(D)Prod-Cong	(E)Falling
Pressure	0			0	2300
Flow Characteristics					
Fall	Y / (N)	Y / N	Y / N	Y / (N)	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	(Y) / N	
Gas or Oil	Y / (N)	Y / N	Y / N	(Y) / N	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Csg had Oil on it bled down to nothing real quick, did mit at same time,
Failed Mit, S.I well

Signature: Darren Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linnenergy.com	
Date: 3/6/14	Phone: 575-369-9113
Witness:	

MAR 31 2014