

MAR 28 2014

RECEIVED

District 1
1623 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Linn Operating	API Number 30-025-32731
Property Name Caprock Maljamar Unit	Well No. 67

2. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
1	19	17S	33E	1945'	FSL	734'	FEL	Lea

Well Status

Well Status	SHUT-IN	PRODUCING	DATE	Injection
			3-11-14	Active

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1)-Interm (2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0			0	2300
Flow Characteristics					
Full	Y / (N)	Y / N	Y / N	(Y) / N	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	Y / (N)	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK

Remarks:

INJECTING AT THIS TIME ☒ WITH ☐ GAS, ☐ CO₂

csg had puff, Braden head good, failed mit S.I injection well

Signature: Darren Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linnenergy.com	
Date: 3-11-14	Phone: 575-369-9113
Witness:	

MAR 31 2014