

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

2014

BRADENHEAD TEST REPORT

RECEIVED

APT Number

30-025-00529

Operator Name

Linn Operating

Property Name

Caprock Maljamar Unit

Well No.

23

2. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
0	13	17S	32E		660'	FSL	1980'	FEL	Lea

Well Status

Well Status	SHUT-IN	PRODUCING	DATE	Injection
			3-14-14	Active

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm 1-Interm 2	(C)Interm-Prod	(D)Prod-Casing	(E)Nothing
Pressure	0			0	2300
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:


INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO₂

A - had nothing

D - Puff

Accepted for Record Only

MSB 3/26/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Darren Scooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dscooter@linenergy.com	
Date: 3-14-14	Phone: 575-369-9115
Witness:	

APR 17 2014

h