

MAR 21 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Linn Operating	API Number 30-025-00667
Property Name Caprock Maljamar Unit	Well No. 62

2. Surface Location

UL - Lot J	Section 24	Township 17S	Range 32E	Feet from 1980'	N/S Line FSL	Feet from 1980'	E/W Line FEL	County Lea
----------------------	----------------------	------------------------	---------------------	---------------------------	------------------------	---------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 3-14-14	Injection Active
-------------	---------	-----------	------------------------	----------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Intern	(B) Intern (1)-Intern (2)	(C) Intern-Prod	(D) Prod Cons	(E) Tubing
Pressure	0			0	0
Flow Characteristics					
Fall	Y / (N)	Y / N	Y / N	Y / (N)	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	Y / (N)	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO₂

Tbg is 0, because well is S.I due to being over max allowable
Add had nothing

Accepted for Record Only

MSB 3/26/2014

Signature: Da Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linnenergy.com	
Date: 3-14-14	Phone: 575-369-9113
Witness:	

APR 17 2014