

MAR 21 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Linn Operating	API Number 30-025-01457
Property Name Caprock Maljamar Unit	Well No. 18

2. Surface Location

UL - Lot 1	Section 18	Township 17S	Range 33E	Feet from 1980'	N/S Line FSL	Feet From 660'	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	---------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 3-14-14	Injection Active
-------------	---------	-----------	------------------------	----------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1)-Interm (2)	(C) Interm-Prod	(D) Prod-Cong	(E) Tailing
Pressure	0			5	2450
Flow Characteristics					2350
Puff	Y / (N)	Y / N	Y / N	Y / (N)	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	(Y) / N	
Gas or Oil	Y / (N)	Y / N	Y / N	(Y) / N	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

RE CHECK
3/26/2014
MSB

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: A- had nothing D- had Gas blew down to nothing	INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2 MSB 3/26/2014
---	--

Signature: D. Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linenergy.com	
Date: 3-14-14	Phone: 575-369-9113
Witness:	

APR 17 2014