

MAR 21 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Linn Operating	APT Number 30-025-01478
Property Name Caprock Maljamar Unit	Well No. 40

2. Surface Location

UL - Lot A	Section 19	Township 17S	Range 33E	Feet from 660'	N/S Line FNL	Feet From 660'	E/W Line FEL	County Log
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 3-14-14	Injection Active
-------------	---------	-----------	------------------------	----------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm 1-Interm 2	(C) Interm-Prod	(D) Prod Casing	(E) Topline
Pressure	0			0	2050
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO₂

ADD - had nothing

Accepted for Record Only

MRS 3/26/2014

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Phone:
	Witness:

APR 17 2014

[Signature]