

HOBBS OCD

MAR 21 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Linn Operating	API Number 30-025-01498
Property Name Caprock Malja mar Unit	Well No. 68

2. Surface Location

UL - Lot L	Section 20	Township 17S	Range 33E	Feet from 1650'	N/S Line FSL	Feet From 990'	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	---------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 3-14-14	Injection Active
-------------	---------	-----------	------------------------	----------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm 1-Interm 2	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0			0	2300
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	Y / (N)	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFOR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO₂

ADD - both had nothing

Accepted for Record Only

YMB 3/26/2014

Signature: Dar Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linnenergy.com	
Date: 3-14-14	Phone: 575-369-9113
Witness:	

APR 17 2014