<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 Phone: (\$75) 393-6161 Fax: (\$75) 393-0720 MAY 01 2014

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT

RECEIVED

Operator Name Cross Timber Energy, LLC								^{3.} API Number 30-025-23782			
Property Name								Well No.			
North Vacuum ABO Unit 157 * Surface Location											
UL - Lot Section Township			Range	Feet from			Feet	From	E/W Line	County	
		178	34E	2180		•		60	FEL	Lea	
Well Status											
Well Status		a	shut-in chilse	WI W		4-16-1		E : 14			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIV							Y FOR	15 MINUTI	ES EACH		
OBSERVED DATA If bradenhead flowed water, check all of the descriptions that apply:											
-		(A)	Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod		(<u>D</u>)	(D)Prod Csng (E)T			
Pressure			0						0 3100		
Flow Characteristics											
Puff		1	′ / 🐿	Y / N	Y / N				Y/80		
Steady F			/ (B) / (B)	Y / N		Y / N			Y / KO Y / YO		
Surges			7/80	Y / N Y / N		Y / N Y / N			Y / (S)	-	
Down to nothing Gas or Oil			/ (b)	Y / N		Y / N			Y / V O	1	
Water			(10	Y / N		Y / N		1	<u> </u>	-	
_				<u> </u>						J	
		heck all of the descriptions that apply:			T .						
CLEAR		FRE	SH 	SALTY	SULFUR			BLACK			
Remarks: INJECTING AT THIS TIME WTR, GAS,									GAS, CO2		
										·	
	•										
BS 5-2-14											
Signature:							OIL CONSERVATION DIVISION				
Printed name: Janos Enbros							Entered into RBDMS				
Title:	leas	$\overline{}$	crator	erator			Re-test				
Date: 4-16-14		1	Phone: (575) 704-2241					1			
			Witness:								

