

MAY 14 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name LINN OPERATING	API Number 30-025-36832
Property Name EAST HOBBS SAN ANDREAS UNIT	Well No. 505

7. Surface Location

UL - Lot J	Section 30	Township 18S	Range 39E	Feet from 1720	N/S Line FSL	Feet From 2340	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN ☒	PRODUCING	DATE 5/13/14
-------------	--	-----------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	2	0
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	Y / (N)	Y / N	Y / N	Y / (N)	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

- TOP JT REPLACED WITH 4' SUB & VALVE.

Accepted for Record Only

MSB 5/14/2014

Pressure Violation - Valves replaced ok.
Per Summary 5/14/2014 - JAS/OCD

Signature: Enrique Contreras	OIL CONSERVATION DIVISION
Printed name: ENRIQUE CONTRERAS	Entered into RBDMS
Title: PROD. SPECIALIST	Re-test
E-mail Address: econtreras@linnenergy.com	
Date: 5/13/14	Phone: 575/909-0031
Witness:	

MAY 14 2014