

MAY 01 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

RECEIVED

Operator Name Cross Timber Energy, LLC	3. API Number 3002529169
Property Name Bridge State Sec 24	Well No. 198

7. Surface Location

UL - Lot m	Section 24	Township 17S	Range 34E		Feet from 1310	N/S Line FSL	Feet From 1310	E/W Line FWL	County Lea
---------------	---------------	-----------------	--------------	--	-------------------	-----------------	-------------------	-----------------	---------------

Well Status

Well Status	SHUT-IN TA well	PRODUCING TA'd well	DATE EXT - 1-14-09
-------------	--------------------	------------------------	-----------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0			41 psi	
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	☒ Y / N	
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	
Down to nothing	Y / ☒ N	Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	☒ Y / N	
Water	Y / ☒ N	Y / N	Y / N	☒ Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

opened csg valve it started spraying oil so I put a psi gauge on. 41psi
got a vac truck to bleed into. well bled down in 30 sec. oil & water
STA Status Expired.
211814 SAN/OCD-
BS 5-2-14

Signature: 	OIL CONSERVATION DIVISION
Printed name: James Embree	Entered into RBDMS
Title: Lease Operator	Re-test
E-mail Address: Tembre@CTFieldSUCS.com	
Date: 4-16-14	
Phone: (575) 704-2241	
Witness:	

MAY 14 2014

h.