

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

MAY 21 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name DKD LLC	API Number 30-025-27886
Property Name RICHARDSON FEE SWD	Well No. #2

7. Surface Location

UL - Lot K	Section 5	Township 14S	Range 36E	Feet from 1980	N/S Line S	Feet From 1980	N/W Line W	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status IN	SHUT-IN SWD	PRODUCING 5/21/14	DATE SWD ACTIVE
--------------------------	-----------------------	-----------------------------	---------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0			0	VAC
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

VAC ON TUBING

PS 5/23/2014

Signature: Danny R Watson	OIL CONSERVATION DIVISION
Printed name: DANNY R WATSON	Entered into RBDMS
Title: PRES.	Re-test
E-mail Address:	
Date: 5/21/14	Phone:
Witness:	

MAY 27 2014