Submit One Copy To Appropriate District Office	State of New Mexico		Form C-103
District I Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO. 30.025201444	
District II 811 S. First St., Grand Ave., Artesia, NM 88210 HOBBS COID CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Type of Lease
$\frac{District III}{1000 \text{ Rio Brazos Rd., Aztec, NM 87440}} N 02 2014 Santa Fe, NM 87505$			STATE FEE FED 6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM			
87505 RECEIVED SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			CAPROCK MALJAMAR UNIT
1. Type of Well: Oil Well Gas Well Other Injection			8. Well Number 010
2. Name of Operator LINN OPERATING, INC.			9. OGRID Number 269324
3. Address of Operator			10. Pool name or Wildcat MALJAMAR;GRAYBURG-SAN
600 TRAVIS STREET, SUITE 5100 HOUSTON, TX 77002			ANDRES
4. Well Location			
Unit Letter $\underline{F} : \underline{1980}$ feet from the <u>NORTH</u> line and $\underline{1980}$ feet from the <u>WESH</u> line Section $\underline{17}$ Township <u>17S</u> Range $\underline{33E}$ NMPM County LEA			
Image of the section of the sectio			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTER			SEQUENT REPORT OF:
	UG AND ABANDON	REMEDIAL WORK	
—		CASING/CEMENT	
OTHER:			eady for OCD inspection after P&A
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 			
\square A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u> PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with 			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.) All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
\boxtimes Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- retrieved flow lines and pipelines. \bigotimes \bigvee			
SIGNATURE Juna A Mretty TITLE Regulatory Compliance Advisor DATE 5/27/2014			
TYPE OR PRINT NAME Laura A. Moreno E-MAIL: <u>lmoreno@linnenergy.com</u> PHONE: <u>713-904-6657</u> For State Use Only Image: Comparison of the second se			
Mad (Hid L Con alian Africa - alian Ali			
APPROVED BY: Mal White TITLE Compliance Officer DATE 06/03/2014 Conditions of Approval (if any): JUN # 4 2014			