

JUN 11 2014

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-07408
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 141

7. Surface Location

UL - Lot M	Section 27	Township 15-S	Range 38-E	<input checked="" type="checkbox"/>	Feet from 330	N/S Line SOUTH	Feet From 287	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	-------------------------------------	------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING <input checked="" type="checkbox"/>	DATE 5-21-14	Water Flood Prod Water Flood Prod
-------------	---------	--	-----------------	--------------------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	Ø	Ø	Ø	36	80
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

FOR RECORD ONLY

Ben Hubbard

BS 6/12/2014

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: 5/29/2014	Phone: 806-592-6280
Witness:	

JUN 18 2014