HOBBS OCD

State of New Mexico

JUN 1 2 2014

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name OCCIDENTAL PERMIAN, LTD									30-025-37266.			
Property Name SOUTH HOBBS (G/SA) UNIT									Well No. 243			
				^{7.} S	urface Locat	ion						
UL - Lot F	Section 4	' " .		Feet from 1660			Feet From 2106	E/W Line WEST	County LEA			
· · · · · · · · · · · · · · · · · · ·				•	Well Status	S			•	· · · · · · · · · · · · · · · · · · ·		
Well Status SHUT-IN PRODUCING O								DATE 2-14	Worl	ef bod Pana		
L	OPE	N BRADEN	HEAD AND INT	ERMEDIATE 1						F.) 300 4 1 6 19 (1)		
If bradenhead	d flowed wa	ter, check al	of the description		SERVED DA	ΛTA		•				
If bradenhead flowed water, check all of the descriptions that apply: (A)Surf-Interm (B)Interm(1)-Interm(2) (C)Interm-Prod								(D)P	rod Csng	(E)Tubing		
Pressure					MA		NA		105	90		
Flow Characteristics			7						//			
Puff		-	Y / N	Y	/ N	 	Y / N		Y / N	-		
Steady Flow			Y / N	Y	/ N	 	Y/N		Y / N			
Surges			Y/N	Y/N		Y/N			Y / N	-		
Down to nothing			Y / N	Y/N		Y/N			Y / N	7		
Gas or Oil			Y / N	Y / N		Y / N			Y / N	7		
Water			Y/N	Y/N		Y/N			Y / N			
If bradenhead	l flowed wa	FRE	of the description		SALTY		SULFUR		BLACK			
Remarks:						INJEC		OR RE	wtr,	gas,co2)NLY		
	J	3~ C	Viulb	ul			B	S 61	23/201	4		
Signature:	Signature: Mendy Johnson									OIL CONSERVATION DIVISION		
Printed name									Entered into RBDMS			
Title: ADMINISTRATIVE ASSOCIATE								Re-test				
E-mail Address: mendy_johnson@oxy.com										//		
Date: 4 11 2014 Phone: 806-592-6280								_				
•		• •	Witness:							₩		