

JUN 12 2014

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

|                                          |                            |
|------------------------------------------|----------------------------|
| Operator Name<br>OCCIDENTAL PERMIAN, LTD | API Number<br>30-025-12765 |
| Property Name<br>SOUTH HOBBS (G/SA) UNIT | Well No.<br>87             |

7. Surface Location

|               |               |                  |               |                                     |                   |                   |                   |                  |               |
|---------------|---------------|------------------|---------------|-------------------------------------|-------------------|-------------------|-------------------|------------------|---------------|
| UL - Lot<br>K | Section<br>10 | Township<br>19-S | Range<br>38-E | <input checked="" type="checkbox"/> | Feet from<br>1650 | N/S Line<br>SOUTH | Feet From<br>2310 | E/W Line<br>WEST | County<br>LEA |
|---------------|---------------|------------------|---------------|-------------------------------------|-------------------|-------------------|-------------------|------------------|---------------|

Well Status

|             |         |                                     |                         |
|-------------|---------|-------------------------------------|-------------------------|
| Well Status | SHUT-IN | PRODUCING<br><i>active injector</i> | DATE<br><i>6-4-2014</i> |
|-------------|---------|-------------------------------------|-------------------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Casing | (E)Tubing   |
|----------------------|----------------|------------------------|----------------|----------------|-------------|
| Pressure             | <i>Puff</i>    | <i>0</i>               | <i>N/A</i>     | <i>30</i>      | <i>1095</i> |
| Flow Characteristics |                |                        |                |                |             |
| Puff                 | <i>0</i> / N   | Y / N                  | Y / N          | Y / N          |             |
| Steady Flow          | Y / N          | Y / N                  | Y / N          | Y / N          |             |
| Surges               | Y / N          | Y / N                  | Y / N          | Y / N          |             |
| Down to nothing      | <i>0</i> / N   | Y / N                  | Y / N          | <i>0</i> / N   |             |
| Gas or Oil           | Y / N          | Y / N                  | Y / N          | Y / N          |             |
| Water                | Y / N          | Y / N                  | Y / N          | Y / N          |             |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

*Surface puff to 0. Prod. casing bleed to 0 Sec.*

*Jessie Schaffer* FOR RECORD ONLY

*PS 6/23/2014*

|                                              |                           |
|----------------------------------------------|---------------------------|
| Signature: <i>Mendy Johnson</i>              | OIL CONSERVATION DIVISION |
| Printed name: MENDY JOHNSON                  | Entered into RBDMS        |
| Title: ADMINISTRATIVE ASSOCIATE              | Re-test                   |
| E-mail Address: <i>mendy_johnson@oxy.com</i> |                           |
| Date: <i>6/11/2014</i>                       | Phone: 806-592-6280       |
| Witness:                                     |                           |

JUN 24 2014