

JUN 13 2014

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-07678 ✓
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 76 ✓

7. Surface Location

UL - Lot E	Section 10	Township 19-S	Range 38-E	✓	Feet from 1980	N/S Line NORTH	Feet From 660	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	---	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 5-20-14
-------------	---------	-----------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod (Casing)	(E) Tubing
Pressure	could not open	Cmt	0 lbs	100 lbs	1054
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ✓ WTR, GAS, CO2

~~Surf Interm valve need to be replaced.~~

could not open

that  
~~Surf Interm~~ Cmt

FOR RECORD ONLY

Alan W. Hubbard

BS 6/24/2014

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: <u>mendy_johnson@oxy.com</u>	
Date: <u>6/12/2014</u>	
Phone: 806-592-6280	
Witness:	

JUN 26 2014