

JUN 26 2014

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name COG Operating LLC	API Number 30-025-39519 ✓
Property Name Maljamar SWD 29 ✓	Well No. 1

2. Surface Location

UL - Lot 0	Section 29	Township 17S	Range 32E	✓	Feet from 490	N/S Line South	Feet From 2160	E/W Line East	County Lea
---------------	---------------	-----------------	--------------	---	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN ✓	PRODUCING	DATE 4-30-14
-------------	--------------	-----------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Conn	(E)Tubing
Pressure	D			80	0
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	(Y) / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Will be doing well work to repair packer.
* Sergio 7/2/14 - P/S/OC.
Well has been repaired

RECORD ONLY

BS 6/27/2014

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Phone:
Witness:	

JUL 02 2014