

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

JUN 26 2014

BRADENHEAD TEST REPORT

Operator Name PROVIDENCE ENERGY SERVICES, INC., dba Kelton Operating	RECEIVED 30-025-32113 ✓
Property Name SKELLY PENROSE B UNIT	Well No. 72 ✓

7. Surface Location

UL - Lot B	Section 5	Township 23S	Range 37E	✓	Feet from 1220	N/S Line NORTH	Feet From 1370	E/W Line EAST	County LEA
---------------	--------------	-----------------	--------------	---	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING A-OIL	DATE 06/14/2014
-------------	---------	--------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure				36#	36#
<u>Flow Characteristics</u>					
Puff	N	Y / N	Y / N	Y / N	
Steady Flow	N	Y / N	Y / N	Y - N	
Surges	Y / N	Y / N	Y / N	Y - N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	N	Y / N	Y / N	Y / N	
Water	N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Cemented to the surface.

OR RECORD ONLY

Bf 6/27/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: C. DALE KELTON	Entered into RBDMS
Title: PRESIDENT	Re-test
E-mail Address: providenceenergy@suddenlink.net	
Date: 06/16/2014	Phone: 432-661-1364
Witness:	

JUL 08 2014