

HOBBS OCD

JUL 01 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-28926
Property Name Seven Rivers Queen Waterflood, North	Well No. 13

7. Surface Location

UL - Lot K	Section 4	Township 22S	Range 36E	Feet from 1325	N/S Line South	Feet From 1330	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING <i>injection</i>	DATE
-------------	---------	-------------------------------	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	<i>0</i>			# <i>110</i>	# <i>460</i>
Flow Characteristics					
Puff	Y / <i>(N)</i>	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	<i>(Y)</i> / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	<i>(Y)</i> / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	<i>(Y)</i> / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR. ☐ GAS, ☐ CO2

Well SI at this time waiting on Pulling Unit
to Repair Packer Leak.

Rig on Hole 3/21/2013 MIT being performed 3/25/2014

Bill Sonamaker (NM OCD) Rep approved successful MIT
ON 3/25/2014.

FOR RECORD ONLY

BS 7/2/2014

Signature: <i>Fernando Espino</i>	OIL CONSERVATION DIVISION
Printed name: <i>Fernando Espino</i>	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: <i>3/14/2014</i>	Phone:
Witness:	

JUL 08 2014