Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103
Office <u>District I</u> – (575) 393-6161	strict I – (575) 393-6161 Energy, Minerals and Natural Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88248 OCD District II – (\$75) 748-1283 HOBBS OCD		WELL API NO. 30-025-41436	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, District IV - (505) 476-3460 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE FEE	
1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			BETTIS 20 STATE COM
PROPOSALS.) 1. Type of Well: Oil Well			8. Well Number 002H
2. Name of Operator MURCHISON OIL & GAS, INC.			9. OGRID Number 15363
3. Address of Operator 1100 MIRA VISTA BLVD., PLANO, TX 75093			10. Pool name or Wildcat TRIPLE X; BONE SPRING, WEST
4. Well Location			
Unit Letter P: 200 feet from the S line and 940 feet from the E line			
Section 20 Township 24S Range 33E NMPM LEA County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3531' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON			
PULL OR ALTER CASING			r JOB 🔲
DOWNHOLE COMMINGLE			
OTHER:		OTHER: PERFO	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
04/29/14: Frac 1 stage w/Baker from 15,500'-15,770'; used 241,705 lbs sand, 4,906 bbls treated water & 61 bbls acid. Unable to proceed with frac due to obstruction at 12,150'.			
06/05/14: Ran casing inspection log and found split in 5.5" casing at 12,150'.			
out of 14. Ran easing hispection log and round spite in 5.5 casing at 12,150.			
06/16/14: Set CIBP at 10,600' and covered w/64' cement. Top of cement at 10,536'.			
Snud Date: 03/16/2014		04/18/2014	
Spud Date: 03/16/2014	Rig Release Da	ate: 04/18/2014	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Work // SIGNATURE WP & COO DATE 06/24/2014			
Type or print name Michael S. Daugherty E-mail address: mdaugherty@jdmii.com PHONE: 972-931-0700 For State Use Only			
10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
APPROVED BY: TITLE Petroleum Engineer DATE // /O//F			