

JUN 11 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

| | |
|--|----------------------------|
| Operator Name OCCIDENTAL PERMIAN, LTD | API Number 30-025-05492 |
| Property Name NORTH HOBBS (G/SA) UNIT | Well No. 431 |

7. Surface Location

| | | | | | | | | | |
|---------------|---------------|------------------|---------------|--|-------------------|-------------------|------------------|------------------|---------------|
| UL - Lot 1 | Section 25 | Township 18-S | Range 37-E | | Feet from 2310 | N/S Line SOUTH | Feet From 330 | E/W Line EAST | County LEA |
|---------------|---------------|------------------|---------------|--|-------------------|-------------------|------------------|------------------|---------------|

Well Status

| | | | | |
|-------------|---------|-----------|-----------------|-----------|
| Well Status | SHUT-IN | PRODUCING | DATE 5-22-14 | Act. Inj. |
|-------------|---------|-----------|-----------------|-----------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

| | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Casing | (E)Tubing |
|----------------------|----------------|------------------------|----------------|----------------|-----------|
| Pressure | 30 | 0 | | 308 | 1109 |
| Flow Characteristics | | | | | |
| Puff | (Y) N | Y / (N) | Y / N | Y / N | |
| Steady Flow | Y / N | Y / N | Y / N | Y / N | |
| Surges | Y / N | Y / N | Y / N | Y / N | |
| Down to nothing | (Y) N | Y / N | Y / N | Y / N | |
| Gas or Oil | Y / N | Y / N | Y / N | (Y) N | |
| Water | Y / N | Y / N | Y / N | Y / N | |

If bradenhead flowed water, check all of the descriptions that apply:

| | | | | |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Bled Prod. Casing to 93 HAD SOME LIQUID at Surface
So stopped Bleeding @ 93# WILL Get Truck to Test.
> NOT to perform Remedial Work - CIO3 Approved. 4/29/14
> Operator to Submit PT. 5/29/14

John King

| | |
|---------------------------------------|---------------------------|
| Signature: <u>Mendy Johnson</u> | OIL CONSERVATION DIVISION |
| Printed name: MENDY JOHNSON | Entered into RBDMS |
| Title: ADMINISTRATIVE ASSOCIATE | Re-test |
| E-mail Address: mendy_johnson@oxy.com | |
| Date: 5/29/2014 | Phone: 806-592-6280 |
| Witness: | |

JUL 10 2014