

JUN 12 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-07514 ✓
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 121 ✓

7. Surface Location

UL - Lot E	Section 31	Township 18-S	Range 38-E	✓	Feet from 1980	N/S Line NORTH	Feet From 990	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	---	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 5-29-14	ACT. INJ. ✓
-------------	---------	-----------	-----------------	-------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0	—	—	590	972
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Bled Prod Csg to 75#, HAD oily water There so STOPPED
> Letter of Violation 7/9/14
(Ciseng) JAD/OCD
Failure
Jim King BS 6/23/2014

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: <u>mendy_johnson@oxy.com</u>	
Date: <u>6/10/2014</u>	Phone: 806-592-6280
Witness:	

JUL 10 2014