

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUN 13 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-23304
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 243

7. Surface Location

UL - Lot N	Section 28	Township 18-S	Range 38-E	Feet from 750	N/S Line SOUTH	Feet From 1790	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 6-9-14
-------------	---------	-----------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	326	350
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Surface : 0 PSI
B-Interm Steady Flow with Frozen valve can't open or replace valve
FOR RECORD ONLY
> Violation Letter 7/19/2014 (Inspection) JAB/OCD.
Failure BS 6/26/2014

Signature: <u>Mendy Johnson</u>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: 6/12/2014	Phone: 806-592-6280
Witness:	

JUL 10 2014