

JUN 11 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-37101
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 637

7. Surface Location

UL - Lot B	Section 24	Township 18-S	Range 37-E	Feet from 1268	N/S Line NORTH	Feet From 1455	E/W Line EAST	County LEA
---------------	---------------	------------------	---------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 5-22-14	Act. Inj
-------------	---------	-----------	-----------------	----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	200 ⁷⁹	—	—	363	1591
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME WTR, ☒ GAS, ☐ CO2

Bled Prod Csg TO 79# But had steady flow OF H₂O
After 15 sec.

FOR RECORD ON

B8 6/12/2014

SHUT IN well.

FOR REPAIRS 5/29/2014

INITIAL G103 BEING FILED VIA USPOSL SVC.

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: 5/29/2014	Phone: 806-592-6280
Witness:	

JUL 10 2014