

JUL 09 2014

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.		API Number 30-025-30736	
Property Name East Corbin Delaware Unit		Well No. 6	

7. Surface Location

UL - Lot	Section 21	Township 18S	Range 33E	Feet from 779	N/S Line North	Feet From 1943	E/W Line West	County Lea
----------	---------------	-----------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN Shut-In	PRODUCING	DATE 6/9/14
-------------	--------------------	-----------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0		0	360	580
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------


Remarks:

- (A) Opened valve, slight blow, no pressure  
(C) Opened valve, slight blow, no pressure  
(D) Production casing has 360 psi. Well is shut-in waiting on repair.  
(E) Hole in tubing

FOR RECORD ONLY

Field information submitted by Candy Aguilar

BS 7/8/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Stan Wagner		Entered into RBDMS	
Title: Regulatory Analyst		Re-test	
E-mail Address: stan.wagner@eoqresources.com			
Date: 6/26/2014	Phone: 432-686-3689		
Witness:			

JUL 10 2014