

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 09 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name EOG Resources, Inc.		API Number 30-025-30949	
Property Name East Corbin Delaware Unit		Well No. 3	

Surface Location

UL - Lot	Section 16	Township 18S	Range 33E	✓	Feet from 660	N/S Line South	Feet From 1980	E/W Line East	County Lea
----------	---------------	-----------------	--------------	---	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN Active	PRODUCING Injecting ✓	DATE 6/9/14
-------------	-------------------	--------------------------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------


Remarks:

- (A) Opened valve, slight blow, no pressure
(D) Opened valve, flow water for 10 seconds, then down to nothing

FOR RECORD ONLY

Field information submitted by Candy Aguilar

BS 7/8/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Stan Wagner		Entered into RBDMS	
Title: Regulatory Analyst		Re-test	
E-mail Address: stan_wagner@eoqresources.com			
Date: 6/26/2014	Phone: 432-686-3689		
Witness:			

JUL 10 2014