

District I  
1625 N French Dr., Hobbs, NM 88240  
Phone (575) 393-6161 Fax (575) 393-0720

HOBBS OCD

JUL 09 2014

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name EOG Resources, Inc.		API Number 30-025-32915	
Property Name East Corbin Delaware Unit		Well No. 9	

Surface Location

UL - Lot	Section 21	Township 18S	Range 33E	Feet from 1340	N/S Line North	Feet from 990	E/W Line East	County Lea
----------	---------------	-----------------	--------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN Shut-In	PRODUCING	DATE 6/9/14
-------------	--------------------	-----------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0		0	180	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------


Remarks:

- (A) Opened valve, slight blow, no pressure  
(C) Opened valve, no pressure  
(D) Production casing has 180 psi. Well is shut-in waiting on repair.  
(E) Hole in tubing

FOR RECORD ONLY

Field information submitted by Candy Aguilar

BS 7/8/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Stan Wagner	Entered into RBDMS
Title: Regulatory Analyst	Re-test
E-mail Address: stan.wagner@eogresources.com	
Date: 6/26/2014	Phone: 432-686-3689
Witness:	

JUL 10 2014