

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Hobbs District Office

JUL 10 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-29893 ✓
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 222 ✓

7. Surface Location

UL - Lot L	Section 34	Township 18-S	Range 38-E	✓	Feet from 2019	N/S Line SOUTH	Feet From 817	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	---	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN T/A ✓	PRODUCING	DATE 6-9-14
-------------	------------------	-----------	----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	1	NA	NA	0	0
<b>Flow Characteristics</b>					
Puff	(Y) N	Y / N	(Y) N	Y / N	
Steady Flow	Y / (N)	Y / N	Y / (N)	Y / N	
Surges	Y / (N)	Y / N	Y / (N)	Y / N	
Down to nothing	(Y) / N	Y / N	(Y) / N	Y / N	
Gas or Oil	Y / (N)	Y / N	Y / (N)	Y / N	
Water	(Y) N	Y / N	(Y) N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR ✓	FRESH	SALTY	SULFUR	BLACK
---------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

**FOR RECORD ONLY**

*Mark Lamb* *BS 7/11/2014*

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: 7/8/2014	Phone: 806-592-6280
Witness:	

JUL 14 2014