

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	HOBBS CCD	API Number 30-025-28335	✓
Property Name SOUTH HOBBS (G/SA) UNIT	JUL 10 2014	Well No. 131	✓

7. Surface Location

UL - Lot G	Section 4	Township 19-S	Range 38-E	✓	Feet from 1383	N/S Line NORTH	Feet From 2498	E/W Line EAST	County LEA
---------------	--------------	------------------	---------------	---	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING ✓ Pump Problem	DATE 6-26-14
-------------	---------	-----------------------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	N/A	N/A	N/A	25	25
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Cement circulated surface exempt from shut in
For bradenhead survey

FOR RECORD ONLY

Mark Lamb

BS 7/11/2014

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: 7/8/2014	Phone: 806-592-6280
Witness:	

JUL 14 2014