## HOBBS OCD

## **State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office**

JUL 1 0 2014

**BRADENHEAD TEST REPORT** 

RECEIVED

Operator Name OCCIDENTAL PERMIAN, LTD										3. API Number 30-025-28349		
Property Name SOUTH HOBBS (G/SA) UNIT										Well No. 146		
7. Surface Location												
UL - Lot D			ip Range 38-E		Feet from 75		N/S Line NORTH		rom )5	E/W Line WEST	County LEA	
Well Status												
Well	Status		SHUT-IN		PRODUCING			DATE	114			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH												
OBSERVED DATA  If bradenhead flowed water, check all of the descriptions that apply:												
(A)Surf-Interm (B)Interm(1)-Interm(2) (C)Interm-Prod (D)Prod Csng (E)Tubing											(E)Tubing	
Pressure			A/A		NIA		11/A		55051		1,0051	
Flow Characteristics			1011						1 11			
Puff		•	Y/N		Y / N		Y / N		Y / N			
Steady Flow			Y/N		Y / N		Y / N		Y / N			
Surges			Y / N		Y / N		Y / N			Y / N		
Down to nothing			Y / N		Y / N		Y / N		Y / N			
Gas or Oil			Y / N	Y/N			Y/N			Y / N		
Water			Y / N	Y / N			Y/N			Y / N		
If bradenhead flowed water, check all of the descriptions that apply:												
CLEAR		FRE	FRESH SALTY				SULFUR		BLACK			
						1811	COTING	T THE T		WED		
Cencent circulated surface exempt from solut in for broken head survey												
broken head survey												
for record only												
Ma	mad f. f									12014		
1:10	w C g	ZUN V						· -×)	<del>-////</del>	/20/7		
Signature: Menoly Othorn								OIL CONSERVATION DIVISION				
Printed name: MENDY JOHNSON								Entered into RBDMS				
Title: ADMINISTRATIVE ASSOCIATE								Re-test				
E-mail Address: mendy_johnson@oxy.com											<b>f</b>	
	3 201	4	Phone: 806-592-6280									
Witness:										V		
·								<del>.</del>				