

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

JUL 10 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-28356 ✓
Property Name SOUTH HOBBS (G/SA) UNIT	Well No. 153 ✓

7. Surface Location

UL - Lot C	Section 9	Township 19-S	Range 38-E	✓	Feet from 1105	N/S Line NORTH	Feet From 1585	E/W Line WEST	County LEA
---------------	--------------	------------------	---------------	---	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING ✓	DATE 6/23/14
-------------	---------	-------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	N/A	N/A	N/A	75	80
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / (N)	
Steady Flow	Y / N	Y / N	Y / N	(Y) / N	
Surges	Y / N	Y / N	Y / N	Y / (N)	
Down to nothing	Y / N	Y / N	Y / N	(Y) / N	
Gas or Oil	Y / N	Y / N	Y / N	(Y) / N	
Water	Y / N	Y / N	Y / N	Y / (N)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

Cement circulated surface exempt from shut in  
for broken head survey

FOR RECORD ONLY

Mad List

BS 7/11/2014

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: 7/8/2014	Phone: 806-592-6280
Witness:	

JUL 14 2014