State of New Mexico Energy, Minerals and Natural Resources Department

Form C-	103
Revised	5-27-2004

FILE IN TRIPLICATE	uass argu	CONSERV	ATION DIVI	SION			Revised 5-27-2004
DISTRICT I		<b>CONSERVATION DIVISION</b> 1220 South St. Francis Dr.			WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240		Santa Fe, NM 87505		30-025	5-28268	r	
DISTRICT II	JUL <b>01</b> 2014	,			5. Indicate Type	of Lease	
1301 W. Grand Ave, Artesia, NM 88210					STA	TE	FEE X
DISTRICT III	RECEIVED				6. State Oil & Ga	as Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410	RECEIVED						
SUNDRY 1	NOTICES AND REP	ORTS ON WE	LLS		7. Lease Name o	r Unit Agreen	nent Name
(DO NOT USE THIS FORM FOR					North Hobbs (	G/SA) Unit	
DIFFERENT RESERVOIR. USE	E "APPLICATION FOR PI	ERMIT" (Form C-	101) for such proposal	ls.)	Section 33		
1. Type of Well:		-			8. Well No. 4	22	$\checkmark$
Oil Well	Gas Well	Other In	jector		0.00000		
2. Name of Operator					9. OGRID No.	157984	
Occidental Permian Ltd. 3. Address of Operator					10. Pool name or	Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City,	TX 79323					Whiteat	HODDS (U/SA)
4. Well Location	IX 1)525				L		
Linit Latter II - 2191	Fact From The	NT	Lincord 400	Foot	t From The	<b>D</b> 4	Lina
Unit Letter <u>H</u> : <u>2181</u>	Feet From The	North	Line and 498	ree	- From The	East	_ Line
Section 33	Township		Range	<b>38-</b> E	V NMPM	1	Lea County
		ow whether DF, RI	KB, RT GR, etc.)				
	3658' KB						
Pit or Below-grade Tank Application	or Closure						
					D'-t for		£
Pit Type Depth of Gro						m nearest st	irtace water
Pit Liner Thickness mil	Below-Grade Tan	k: Volume	bbls; Const	ruction Mat	terial		
12. Ct	eck Appropriate Box	to Indicate Na	ture of Notice R	enort or C	ther Data		
	NTENTION TO:				SEQUENT RE		E.
	-						_
	PLUG AND ABAN		REMEDIAL WOR			ALTERING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPI	vs.	PLUG & A	
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB							
OTHER:	R: OTHER: Casing Integrity Test			X			
	0						<b></b>
13. Describe Proposed or Completed proposed work) SEE RULE 11							tarting any
proposed work) see KOLE IT	5. For Multiple Compl	enons. Attach v	ventione diagram of	proposed e	ompletion of reet	mpretion.	
Date of Test: 06/06/2014							
Pressure Readings: Initial – 600 Pa	SI; 15 min – 600 PSI;	30 min – 600 P	SI				
Length of test: 30 minutes							
Length of test. 50 minutes			•				
Witnessed: NO							
I hereby certify that the information above	e is true and complete to th	e best of my know	ledge and belief. I fu	rther certify t	hat any pit or below	v-grade tank h	as been/will be
constructed or closed according to NMOCD guideling	nes , a genera		or an (attached)	) alternative	OCD-approved	[	
	, a genera		plan	<i>j</i> anomative	ocu-approved		
	71/101		<b>_</b> .			· · ·	
SIGNATURE	AUAP	VION	Adm	inistrative	Associate	DATI	8 06/27/2014
TYPE OR PRINT NAME Mendy A	Johnson UE-	mail address:	mendy_johnson	@oxy.com	TELE	EPHONE NO.	806-592-6280
For State Use Only							

APPROVED BY Bill Seenamah	TITLE	She Manage DATE	7/8/2014
CONDITIONS OF APPROVAL IF ANY:			
		UL 1 4 2014/	1
		- 2014/	r-



American Valve & Meter, Inc. 1113 W. Broadway P.O. Box 166 Hobbs New Mexico 88240

To: \_Pate Trucking

٩,

Date\_04/09/14

Serial No. MFG3219

This is to certify that:

I\_Bud Collins\_\_\_\_\_\_Technician for American Valve & Meter Inc. has checked

the calibration of the following instrument.

8" pressure recorder\_

at these points.

Pressure # or Temperature\*

Pressure#

			·····			
Test	Found	Left	Test	Found	Left	
- 0	- 0	- 0	-	-	-	
- 500	-	~ 500	-	-	-	
- 700	-	- 700	-	-	•	
- 1000	-	- 1000	-	-		
- 200	-	- 200	-	-	-	
- 0	-	- 0	-	-	-	

Remarks:\_\_\_\_

ud tollan Signature