

JUL 13 2014

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name LRE Operating, LLC	API Number 30-025-01337 ✓
Property Name Corbin ABC SWD	Well No. #031 ✓

2. Surface Location

UL - Lot G	Section 31	Township 17S	Range 33E	✓	Feet from 1980	N/S Line North	Feet From 1980	E/W Line East	County Lea
---------------	---------------	-----------------	--------------	---	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status - A	SHUT-IN	PRODUCING S ✓	DATE 04-17-2014
-----------------	---------	------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0			0	90
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------


Remarks:

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

FOR RECORD ONLY

BS 7/13/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: <a href="mailto:pmealand@linemrockresources.com">pmealand@linemrockresources.com</a>	
Date: 04-23-2014	Phone: 575-623-8424
	Witness:

JUL 16 2014