State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

JUL 13 2014

RECEIVED

BRADENHEAD TEST REPORT									VECEIVED			
Operator Name Lime Rock Resources II-A, L.P.									API Number 30-025-25067			
Property Name North Vacuum ABO North Unit									1	 	Well No.	
بسنسب		<u>-</u>	10111			·		·	<u> </u>		#001 -	
[1] 1 at	Sustina	Tti-	D		7 Surface Loca					Datt :	<u> </u>	
Р	UL - Lot Section Township Range P 35 16S 34E		Feet from 460			I/S Line South	Feet From 660		E/W Line East	County Lea		
		· · · · · · ·			Well Statu	ıs	· · · · · · · · · · · · · · · · · · ·	<u> </u>	·			
Well S	tatus - A		SHUT-IN		PRODUCING Injection			DATE 04-17-2014			····	
If bradenhead				(TE TO ATMOSPH OBSERVED DA		IVIDUALL	Y FOR 15	MINUTES	S EACH		
		(A)Su	(A)Surf-Interm		(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing	
Pressure	Pressure		U					-	0		3800	
Flow Charac	teristics		 	-		1		······································			J	
Pull			Y/N		Y/ N		Y / N		V / N		_	
Steady Flow			Y / N		Y/N		Y7 N		V/N			
Surges			Y / N:		Y/N		Y/N		V/N			
Down to nothing			Y/N		Y/N		Y/N		Y/N			
Gas or Oil Water			Y/N		Y/N		Y / N		Y / N Y / N			
wate		i	Y / N	_	Y/N		Y/N		<u> </u>	· / <u>1</u>	J	
If bradenhead	flowed wat	er, check all	of the descript	ions that app	<u>Y:</u>							
CLEAR		FRES	SH		SALTY SULFO			R		BLACK	BLACK	
			· · · · · · · · · · · · · · · · · · ·	I						!	<u> </u>	
Remarks:												
Tested by Edd Reported by T			424		FO	R RI	ECOF	RD O	NLY			
							138	3 7/	<u> 13/</u>	2014		
Signature: (4m	MAL	olomo	(N DIVISION	
Printed name: Trish Mealand									Entered into RBDMS			
Title: Production Analyst								Re-test				
E-mail Address: pmealand@limerockresources.com									···			
Date: 04-23-2014 Phone: 575-623-8424								-	· · · · · · · · · · · · · · · · · · ·			
Date: 04-23-2	.014		 						 			
Witness:												