

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 13 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-32721 ✓
Property Name North Vacuum ABO North Unit	Well No. #073 ✓

7. Surface Location

UL - Lot G	Section I	Township 17S	Range 34E	✓	Feet from 1980	N/S Line North	Feet From 1980	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	---	-------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status - A	SHUT-IN	PRODUCING Oil ✓	DATE 04-17-2014
-----------------	---------	--------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure			0	70	90
Flow Characteristics					
Puff	N/A	Y / N	Y / N	Y / N	
Steady Flow	N/A	Y / N	Y / N	Y / N	
Surges	N/A	Y / N	Y / N	Y / N	
Down to nothing	N/A	Y / N	Y / N	Y / N	
Gas or Oil	N/A	Y / N	Y / N	Y / N	
Water	N/A	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Surface has cement circulated inside and outside.

FOR RECORD ONLY

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

BS 7/13/2014

Signature: <i>Trish Mealand</i>	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: tmealand@limerockresources.com	
Date: 04-23-2014	Phone: 575-623-8424
Witness:	

JUL 17 2014

h