

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 13 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-29192
Property Name North Vacuum ABO North Unit	Well No. #003

2. Surface Location

UL - Lot O	Section 2	Township 17S	Range 34E	Feet from 460	N/S Line South	Feet From 1680	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status - A	SHUT-IN	PRODUCING Injection	DATE 04-17-2014
-----------------	---------	------------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	N/A		0	200	700
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Failed MIT, shut in well.

FOR RECORD ONLY

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Letter of Violation 7/21/2014
AS/OCD

BS 7/13/2014

Signature: <i>Trish Mealand</i>	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: trishmealand@limerockresources.com	
Date: 04-23-2014	Phone: 575-623-8424
Witness:	

JUL 22 2014

L