

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON		API Number 30-025-24307	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No. 30 -	

Surface Location

UL - Lot K	Section 2	Township 18S	Range 34E	☒	Feet from 2630	N/S Line FSL	Feet From 2630	E/W Line FWL	County LEA
----------------------	---------------------	------------------------	---------------------	-------------------------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	☒ INJ	☒ SWD	OIL	PRODUCER GAS	DATE 5/5/14
------------------	----	----------------	----	---	---	-----	-----------------	-----------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			10	1900
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	☒ N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	☒ N	WTR ☒
Surges	Y / N	Y / N	Y / N	☒ N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	☒ N	
Water	Y / N	Y / N	Y / N	☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) Small amount of gas, bled down to zero. Reviewed 24hrs later pressure still at zero.
FOR RECORD ONLY

BS 7/25/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/10/14	Phone: 575 942-3526		
Witness:			

JUL 30 2014

