

JUL 24 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON						API Number 30-025-24359			
Property Name VACUUM GRAYBURG SAN ANDRES UNIT								Well No. 014	
Surface Location									
UL - Lot K	Section 2	Township 18S	Range 34E	☒	Feet from 1560	NS Line FSL	Feet From 1560	E/W Line FWL	County LEA
Well Status									
TA'D WELL YES ☐ NO ☐		SHUT-IN YES ☐ NO ☐		INJECTOR ☒ IN ☐ SWD		PRODUCER OIL ☐ GAS ☐		DATE 5/5/14	


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	1310
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

B8 7/25/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Doreen McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lmm@chevron.com			
Date: 7/10/14	Phone: 575 942-3526		
Witness:			

JUL 30 2014

