

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 24 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON		API Number 30-025-25994	
Property Name CENTRAL VACUUM UNIT		Well No. 133	

Surface Location

UL - Lot B	Section 12	Township 18S	Range 34E	☒	Feet from 60	N/S Line FNL	Feet From 1550	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------------------	------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	☒ INJ	INJECTOR ☒	SWD	OIL	PRODUCER	GAS	DATE 5/5/14
------------------	----	----------------	----	---	---	-----	-----	----------	-----	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C'sng	(E)Tubing
Pressure	0	0		40	1400
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / ☒ N	CO2 ☒
Steady Flow	Y / N	Y / N	Y / N	☒ Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterhead if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / ☒ N	
Water	Y / N	Y / N	Y / N	☒ Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) packer fluid bled down to zero. Verified 24 hours later that pressure was still zero.

FOR RECORD ONLY

B2 7/25/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McQueen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/14/14	Phone: 575-942-3526		
Witness:			

JUL 30 2014

